



## Interferences

## RPM Cable

---

**Question:**

The manual says to coil RPM cable many times, why AiM does not give this suggestion?

**Answer:**

In 2T engines the signal is strong enough: coiling many times the RPM cable on the sparkplug wire could generate issues, like these described in the FAQ concerning MyChron5/MyChron5S/MyChron6 display.